



# Work Order (Bid Form)

## WORK ORDER INFORMATION

**Work Order Name:** WO/12012NW4063/1

**Work Order Type:** Weatherization

**Audit Name:** Audit-12012NW4063

## CLIENT INFORMATION

**Client Name:** 12012NW4063

**Address:**

**Client ID:** 12012NW4063

, 38242

**Alt. Client ID:** Henry

## CLIENT CONTACT INFORMATION

12012NW4063

Applicant/Person of  
Record



## AGENCY INFORMATION

**Agency:** Northwest TN EDC

**Agency Phone:** (731) 364-3228

**Address:** 231 S. Wilson Street  
Dresden, TN 38225

**Fax:**

**Email Address:**

**Agency Contact:** Radford, Randy

**Work Phone:** (615) 686-3245

**Cell Phone:** (615) 335-7428

**Email Address:** Randy@energyhoundz.com

**Company Name & License Number:** \_\_\_\_\_

**Contractor's Signature:** \_\_\_\_\_

## COMMENT

Contractor to follow the Southeast Field Guide as applicable.

## Measures

Measure 1 Reglaze Window WD1				Components			Inspected		
Comment							<input type="checkbox"/>		
				Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor			1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Windows			1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>
Field Notes:									

Measure 2 Reglaze Window WD7				Components			Inspected		
Comment							<input type="checkbox"/>		
				Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor			1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Windows			1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>
Field Notes:									

**Measure 3 Remove Unused Window A/C from WD6 and Discard****Components****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor			1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Miscellaneous Su			1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

**Other Detail**

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

**Measure Sub Total:****Sub Total:****Field Notes:****Measure 4 Replace Back Door Glass Pane in DR3 (approx. 23.5 x 23.5)****Components****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor			1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Windows			1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

**Other Detail**

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

**Measure Sub Total:****Sub Total:****Field Notes:**

**Measure 5 Weatherstrip Around All Doors****Components****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor			1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Doors			1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

**Other Detail**

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

**Measure Sub Total:** **Sub Total:** **Field Notes:**

**Measure 6 Infiltration Redctn****Components****Inspected**

**Comment** -Air seal around windows  
-Air seal trim around doors  
-Air seal attic access in kitchen pantry (approx. 19 x 5.66)  
-Air seal plumbing penetrations under kitchen sink and behind washing machine  
-Air seal around working window A/C  
-Air seal crack in kitchen floor  
-Air seal around pipe in corner of bathroom at floor, ceiling, and behind pipe on wall  
-Air seal 2 holes under bathroom sink  
-Clear caulk edge of ceiling tile along wall in kitchen (approx. 50 ft), living room (approx. 55 ft), and 1st bedroom (approx. 55 ft)  
-Clear caulk patched hole in middle of kitchen floor

☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Labor								
10	Miscellaneous Su	Infiltration Reduction	Each	1					

**Other Detail**

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

**Measure Sub Total:****Sub Total:****Field Notes:**

**Measure 7 Fill Ceiling Cavity****Components** A1**Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Labor								
1	Insulation	Attic Insulation - Blown Cellulose - 12 in.	SqFt	848					
Other Detail									
Measure Sub Total:							Sub Total:		

**Field Notes:****Measure 8 DWH Pipe Insulation****Components****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
2	Labor	DHW Pipe Insulation	Each	1					
3	Other	DHW Pipe Insulation	Each	1					
Other Detail									
Measure Sub Total:							Sub Total:		

**Field Notes:**

Client Name: 12012NW4063

Client ID: 12012NW4063

Alt. Client ID: Henry

**Work Order (Bid Form)**

Work Order Name: WO/12012NW4063/1

Report Run On: 5/24/2010

DOE Weatherization Assistant

Version 8.6.0

Page 6 of 13

Measure 9 DWH Tank Insulation				Components				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipm	DHW Tank Insulation	Each	1					
2	Labor	DHW Tank Insulation	Each	1					
3	Other	DHW Tank Insulation	Each	1					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 10 Wall Insulation				Components WL2				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Labor								
1	Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	53.5					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

**Measure 11 Wall Insulation****Components** WL3**Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Labor								
1	Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	90.22					
Other Detail									
Measure Sub Total:							Sub Total:		

**Field Notes:****Measure 12 Wall Insulation****Components** WL1**Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Labor								
1	Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	116.7					
Other Detail									
Measure Sub Total:							Sub Total:		

**Field Notes:**

Client Name: 12012NW4063

Client ID: 12012NW4063

Alt. Client ID: Henry

**Work Order (Bid Form)**

Work Order Name: WO/12012NW4063/1

Report Run On: 5/24/2010

DOE Weatherization Assistant

Version 8.6.0

Page 8 of 13



**Measure 13 Wall Insulation****Components** WL7**Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Labor								
1	Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	189.1					

**Other Detail**


**Measure Sub Total:****Sub Total:****Field Notes:****Measure 14 Wall Insulation****Components** WL9**Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Labor								
1	Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	20					

**Other Detail**


**Measure Sub Total:****Sub Total:****Field Notes:**

Client Name: 12012NW4063

Client ID: 12012NW4063

Alt. Client ID: Henry

**Work Order (Bid Form)**

Work Order Name: WO/12012NW4063/1

Report Run On: 5/24/2010

DOE Weatherization Assistant

Version 8.6.0

Page 9 of 13

**Measure 15 Wall Insulation****Components** WL5**Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Labor								
1	Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	20					

**Other Detail**


**Measure Sub Total:****Sub Total:****Field Notes:****Measure 16 Wall Insulation****Components** WL4**Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Labor								
1	Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	154.6					

**Other Detail**


**Measure Sub Total:****Sub Total:****Field Notes:**

Client Name: 12012NW4063

Client ID: 12012NW4063

Alt. Client ID: Henry

**Work Order (Bid Form)**

Work Order Name: WO/12012NW4063/1

Report Run On: 5/24/2010

DOE Weatherization Assistant

Version 8.6.0

Page 10 of 13

**Measure 17 Wall Insulation****Components** WL10**Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Labor								
1	Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	195.9					

**Other Detail**


**Measure Sub Total:****Sub Total:****Field Notes:****Measure 18 Wall Insulation****Components** WL8**Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Labor								
1	Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	86					

**Other Detail**


**Measure Sub Total:****Sub Total:****Field Notes:**

Client Name: 12012NW4063

Client ID: 12012NW4063

Alt. Client ID: Henry

**Work Order (Bid Form)**

Work Order Name: WO/12012NW4063/1

Report Run On: 5/24/2010

DOE Weatherization Assistant

Version 8.6.0

Page 11 of 13

**Measure 19 Wall Insulation****Components** WL6**Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Labor								
1	Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	73.56					
Other Detail									
Measure Sub Total:							Sub Total:		

**Field Notes:****Measure 20 CO Monitor is Needed****Components****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	CO monitor	Each	1					
2	Labor	Labor	Hour	1					
Other Detail									
Measure Sub Total:							Sub Total:		

**Field Notes:**

Client Name: 12012NW4063

Client ID: 12012NW4063

Alt. Client ID: Henry

**Work Order (Bid Form)**

Work Order Name: WO/12012NW4063/1

Report Run On: 5/24/2010

DOE Weatherization Assistant

Version 8.6.0

Page 12 of 13

**Measure 21 Smoke Detector is Needed****Components****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Smoke detector	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

**Other Detail**

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

**Measure Sub Total:** **Sub Total:** **Field Notes:****Work Order Grand Total:** **Grand Total:**